




Brazing in five *easy* steps...




1 Clean the pipe to a bright finish




2 Load the gun with a pin and ferrule



3 Adjust as necessary



4 Braze



5 Test the connection